

Overview

Photos

Usage

Theft

Odometer

Financial and legal status

Damage

Specs & equipment

Timeline



Volkswagen Passat

VIN: 1VWBN7A35CCXXXXXX

2014



Theft



Usage



Odometer



Financial and legal status



Damage



+31

Data sources

We checked 900+ data sources in 35 countries



Driver & Vehicle
Licensing
Agency



Driver & Vehicle
Standards
Agency

Partners

Fuelling this report



Photos

2017-04

8 photos



↑ Close

Usage

Was the vehicle used as a taxi, rental or other service vehicle? Note: such vehicles may be in worse condition than usual!



Vehicle was used as a rental!

Here's what we checked:



Rental

 Record found

Rental vehicle



Taxi

 No record found

No evidence of being used as a taxi



Transport

 No record found

No evidence of being used as a transport vehicle




Police

 No record found

No evidence of being used by police



Handicap

 No record found

No evidence of being used as a handicap vehicle



Driving school vehicle

 No record found

No evidence of being used as a driving school vehicle

↑ Close

Theft

Is the vehicle currently marked as stolen?
Was it stolen in the past? Has it been
recovered?



Vehicle may be stolen!

Here's what we checked:




Currently wanted as stolen ?

 Record found

Unknown date  United Kingdom



Stolen in the past ?

 No record found

Current status unknown



Stolen in the past ?

 No record found

Vehicle has been recovered

Police database stolen vehicle check completed in:



United Kingdom

 Record found



Czechia



Hungary



Italy



Lithuania





Norway


↑ Close


Odometer

Are there signs of mileage roll backs or discrepancies?


 This vehicle may have a fake mileage!

 Last known mileage: 145,000 mi

 Average mileage for similar models: 104,200 mi

 5 mileage records found

 Roll back



↑ Close

Financial and legal status

Has the vehicle passed its technical inspections? Does it have property rights restrictions or outstanding loans?


 Tech inspection is valid

Legal



MOT (technical inspection)

Passed 2017-02

 United Kingdom

Has successfully passed technical inspection



Scrap

✓ No record found

No record that vehicle was marked as scrapped



Exported

Record found 2019-09



Imported

✓ No record found

No import records found

Outstanding finance



Lease ?

✓ No record found

No data available on outstanding loan or finance agreement



Operating-lease ?

✓ No record found

No record of vehicle being on an operating-lease



Unit-stocking ?

✓ No record found

No record of vehicle being under unit-stocking finance

↑ Close

Damage

Has this vehicle been damaged in the past?

What was the value of the damages?



This vehicle was damaged 3 times!



Mild damages normally won't impact a vehicle's safety or leave structural issues

Damage records



Damage

 2018-03

Estimated repair cost

£9,200 ?

Possible damage cause

Unknown

Damage

 2015-07


Estimated repair cost

£2,400

Possible damage cause

Unknown

Damage

 2014-02

Estimated repair cost

£1,000

Possible damage cause

Unknown



Specs & equipment

What specs and equipment are on record for this vehicle?

Check whether the specs and equipment of this vehicle match the facts given by the seller.

Identification and technical specifications

Make Volkswagen	Model Passat	Body Type Sedan
Manufacture year 2014	Powertrain displacement 2 l	Powertrain power 103 kW (138 hp)
Gearbox type Automatic	Plant location Germany	

Equipment

- EGA**
Special editions
No special edition
- 201**
Vehicle class differentiation units/platform components
Vehicle class differentiation -360-
- 1D0**
Trailer hitch
Without trailer hitch
- 4E1**
Activated carbon canister
Activated carbon canister
- 6X0**
Exterior mirrors
automatically dimming, electrically adjustable, separately heated
- 3SL**
Left exterior mirror
spherical
- 1A0**
Drive layout
Front wheel drive
- 4B8**
Equipment levels
Basic equipment
- 49L**
Batteries
Battery 340 A (70 Ah)
- 4M3**
Beverage holders
Cup holder
- 86A**
Component part sets with country-specific design requirements
Component parts set without country-specific design requirement
- 1AT**
Brake systems
Electronic stabilization program (ESP)
- 5Z0**
Operating voltage
Operating voltage 12V
- 7QA**
CD ROM/DVD/SD card
Without CD/DVD/SD card
- 2H0**
Charism
Without "drive select"
- 628**
General operating permit, alterations
Operating permit, alteration
- 3FA**
Roof insert/convertible top
Without roof insert (standard roof)
- 607**
Suspension system in front
Front shock absorption
- 2G1**
Insert for the filling up of unleaded fuel/fuel type
Insert for the filling up of unleaded fuel
- 7AL**
Theft protection system
Anti-theft alarm system, passenger compartment control, backup horn and towing protection
- 7M0**
Scuff plates
Plastic scuff plates in door apertures
- 4FG**
Electric interface for external use
Without electric interface
- 4A0**
Fire extinguishers
Without fire extinguisher
- 8K3**
Headlight control
Separate daytime running lights with low beam assistant and "Coming Home" feature
- 7G0**
Vehicle tracing system
Without preparation for VTS (vehicle tracking system)
- 6G6**
Alternators
Alternator 110 A
- 5VC**
Weight category rear axle
Weight range 3 installation control only, no requirement forecast
- 7U0**
Base engine
4-cylinder gasoline engine 1.4 L unit 03C.K
- 8T0**
Cruise control system
Without cruise control system (CCS)
- 60K**
Transmission specifications
6-speed manual transmission
- 3P1**
Brackets
Bracket for first aid kit and warning triangle
- 4H6**
Heating and air conditioning system
Electronically controlled air conditioning system
- 7CD**
Customized installation
Without customized installation
- 49A**
Instrument clusters
Instrument insert, km/h speedometer
- 49B**
Body style
Notchback
- 6SE**
Luggage compartment floor covering
Flat needle-punched trunk floor covering
- 6AG**
Child seats
Without child seat
- Q80**
Compass/road sign display
Without compass/traffic sign display/ traffic signs recognition
- 3Q6**
Rear head restraints
Three rear headrests
- 1Z0**
Fuel quantity for initial filling
Initial standard fuel filling
- 5C0**
Body measures
Without special body measures
- 4P1**
Rear license plate carrier
License plate bracket rear (ECE)
- 5K7**
Paint preservative/transit coating
Transport protection film (minimum protection) with additional transport protection measures
- FE0**
Country codes
Without country code (no DVD player in vehicle)
- 6S7**
Reading light
Two reading lights front
- 3H0**
Backrest release
Without backrest release for front seats
- 2P1**
Loading edge protection
Plastic trunk sill protection
- 1MR**
Steering wheels
Leather steering wheel
- 8BM**
Speaker installation
8 speakers (passive)
- 6E3**
Center armrest
Front center armrest
- 315**
Center console
Center console
- 6Z5**
Engine cooling system
Not hot country
- 4SG**
Left vanity mirror
Left vanity mirror illuminated extractable sun visor
- 7QR**
Navigation device
Without navigation device
- 8WA**
Front fog lamp/additional headlamp
Without front fog light
- 6Z0**
Wheels
Steel wheels 6.5J x 16 with optimized weight
- 9JA**
Smoker's/non-smoker's package
Non-smoking package
- 4NS0**
Umbrella
Without umbrella(s)
- 4BA**
Tire suppliers
Tires w/o specification of tire brand
- 3QT**
Restraint systems, front
3-point seat belts with tensioner and height adjustment, front
- 4GA**
Anti-theft alarm system "Plus"
True
- 4X3**
Side airbag
Side air bag front with curtain air bag
- 2SB**
Special labels/plates
Labels/plates in Polish, Estonian, Latvian, Lithuanian, Slovenian
- 4E2**
Lock operation for tailgate/trunk lid
Tailgate/trunk lid release from inside (electrically)
- 3SB**
Front seat, right
Standard seat, front right
- 3ZB**
Outer rear seat belts
3-point seat belts, outer rear with ECE label
- 4AC**
Seat trim covers
Fabric seat covering
- 4A0**
Seat heater
Without seat heater
- 8Y1**
Horns
Two-tone horn
- 710**
Lane change assist/lane keeping system
Without lane change assistant
- 4B1**
Protective side molding
Protective side molding
- 7BE**
Socket
12-volt socket(s)
- QW0**
Drawers under front seats
Without drawers under front seats
- 8H3**
Windshield wiper intermittent control/light/rain sensor
Windshield wiper intermittent control with rain sensor
- 4AG**
Nameplate set
Nameplate set in base trim
- 1Q0**
Mass damper for steering wheels
Without mass damper for steering wheel
- 847**
Type approval countries/countries with special requirements
Type approval the Baltic States
- 3CA**
Partition
Without partition
- 3LC**
Door and side trim panels
Door and side trim panel in foam film and woven fabric
- 4VG**
Installation parts for engine (engine mount system)
Installation parts for four-cylinder engine
- 1EX**
Identification plates
Special identification plate for EC for M1 passenger vehicle
- 1T2**
First aid kit / warning triangle
Warning triangle
- 9F0**
Preparation for sound combination for rotating beacon
Without sound combination for rotating beacon and radio antenna preparation
- 9TC**
Additional warning lights
Additional reflectors (door area)
- 7ED**
Heat accumulator system/auxiliary heater
W/o heat accumulator/auxiliary heating
- 8FA**
Second battery/battery installation
Without second battery

- 1PA**
Lockable wheel bolts
Standard wheel bolts
- 7HG**
Emissions standard
Emissions standard EUS
- 4UE**
Airbag
Air bag for driver and front seat passenger
- 6ZH**
Antennas
Antenna for AM/FM reception, "diversity"
- EA0**
Follow-on warranty
Without subsequent warranty
- 8RC**
Right exterior mirror
convex
- 9WL**
"Multimedia", video/DVD/notebook connection
Multimedia socket for external audio source
- 1KW**
Brake type in rear
Disc brakes, rear
- 1ZM**
Brake type, front
Disc brakes, front (Geomet D)
- NV9**
Battery/alternator capacity
Standard battery/alternator capacity
- 1S1**
Tool kit and jack
Tool kit and jack
- 00R**
Owner's manuals
Information kit in Lithuanian
- 8TA**
Heated washer nozzles
Without heated washer nozzles
- 7M0**
CD changer/CD player
Without CD changer/CD player
- QJ1**
Chrome package
Chrome work package
- 350**
Roof rails/roof load rack
Without roof rails/roof load rack
- 1JA**
Suspension system in rear
Rear shock absorption, basic design 1
- 3X0**
Ski bag
Without load-through provision
- 0EM**
Installation differentiation for vehicle components
Installation differentiation for transmission MQ 200 vehicle components
- 7TM**
Inserts
Decorative inserts
- 7X0**
Park distance control
Without park distance control
- 0FG**
Manufacturing sequence differentiation
Mosel manufacturing sequence
- 4V0**
Pedal cluster
Standard pedal cluster
- UH2**
Parking brake
Parking brake
- F0A**
Vehicle specifications
No special purpose vehicle, standard equipment
- 0G4**
Transmission types/gearshift mechanisms
Cable gearshift
- 101**
Weight category front axle
Suspension range 01 installation control only, no requirement forecast
- 6MG**
Tie down straps/net/pocket
Without tie down straps/net/pocket
- 7C0**
Garage door opener
W/o remote-controlled garage door opener
- 07B**
Cruise control system and speed limiter
W/o cruise control speed limit system
- 3NU**
Rear seats
Rear seat bench unsplit, backrest split folding with center armrest
- 8ID**
Headlamps
Halogen twin headlights
- 6T0**
Interior light in footwell
Without interior light in footwell
- 4L8**
Breakaway interior rearview mirror
Breakaway interior rear view mirror, automatically dimming
- QMG**
Camera/distance sensor
Without camera without distance sensor (driver assistance system)
- 4W0**
Cassette and CD storage unit
Without cassette and CD storage unit
- 07Z**
Climatic zones
Cold zones
- 4D0**
Seat ventilation/massage seat
Without seat ventilation/massage seat
- 5Z1**
Head restraints
Front headrests
- 1A2**
Fuel systems
Fuel system for SI engine with direct injection (FSI)
- 8K1**
Radiator grille
Radiator grille with chrome-plated strip
- 6W1**
Front license plate carrier
License plate bracket front (large)
- 3GA**
Rear luggage/load compartment floor
Without cargo area
- 10L**
Steering system arrangement
Right hand drive vehicle
- 1N3**
Steering
Speed-related variable steering assist (Servotronic)
- 8G0**
Light control systems
Without light assistant
- 7P0**
Lumbar support
Without lumbar support in seat backrests
- AV1**
Driving on the left/on the right
Driving on the right
- 8QL**
Headlight range control
Headlight-range adjustment
- 3QB**
Multi-function display/trip computer
Multi-function display with control
- EM0**
Driver alert system
Without Rest Assist
- D4X**
Engine specifications
4-cyl. gasoline engine 1.4 l/90 kW TSI Base engine is TU0/TL1/TL4/T98
- 4TL**
Right vanity mirror
Right vanity mirror, right, illuminated extractable sun visor
- 8TC**
Rear fog lamp
Rear fog light for driving on the right
- 1NH**
Wheel covers
Full wheel covers
- 8AE**
Radio
Radio "RCD310 MP3"
- 7R6**
Direct tire pressure monitoring system
Flat tire indicator
- H2F**
Tires
Tires 205/55 R16 91H super-optimized rolling resistance
- 1G2**
Spare wheel/breakdown kit
Steel spare wheel with original equipment tires
- PA1**
Leather steering wheel (3-spoke) with decorative aluminum inserts
True
- WFA**
Family package, Passat station wagon, Sweden
True
- 6Q2**
Gearshift knob/handle
Leather gearshift knob/handle
- 8SG**
Rear combination lamps
Standard taillight assemblies (type 2)
- 3TB**
Front seat, left
Standard seat, front left
- 8PI**
Seat belt check
Seat belt reminder, electric contact in buckle
- 3CT**
Center rear seat belts
3-point seat belt for center rear seat
- 3L3**
Seat adjustment
Manual height adjustment for front seats
- 7L3**
Start-stop system/regenerative braking
Without start/stop system without regenerative braking
- QW0**
Audio-response system/voice control
Without voice control
- 4RC**
Side and rear windows
Side and rear windows in heat-insulating glass
- 3Y0**
Roll-up sun screen for rear and side windows
Without roll-up sun screen
- 2JB**
Bumpers
Standard bumpers
- 8X0**
Headlamp washer system
Without headlight washer system
- 3M0**
Special registration measures
Without special measures
- 6A0**
Special alarm systems
Without taxi alarm system
- 4K3**
Door and lid locking system
Radio remote controlled central locking operated from inside and safe securing
- 8D1**
Carrier frequency for radio remote control
Carrier frequency 433.92 MHz-434.42 MHz
- 1NT0**
Transit coating
Transit coating (type 1)
- QW0**
TV reception/digital radio reception
W/o TV reception/digital radio reception
- 1SA**
Front underbody guard
Without additional front underbody guard
- 290**
Delivery equipment
Without delivery equipment
- 8D0**
Preparation for two-way radio installation
Without preparation for two-way radio installation
- 9WB**
Telephone / telematics
W/o car phone preparation/installation
- Q01**
Service interval prolongation
Service interval prolongation
- 4GF**
Windshield glass type
Windshield in heat-insulating glass
- 2WA**
Additional tires (snow tires)
Without additional tires
- Decorative trims**
- Black moldings**
- Auxiliary heater**
- Without auxiliary/parking heater**

Close

Timeline

5 records found

The timeline of records for this vehicle

Latest records

2014-01


 Germany



Was manufactured

The country indicates either the location of manufacturing facility, assembly plant or registration address of the manufacturer. The date may be approximate.

2014-02


 United Kingdom



Was registered

The record represents an administrative event. This could be related to a change of ownership, documents, etc

2017-02

 United Kingdom



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2018-03


 United Kingdom



Damage detected

We have indications that this vehicle was recognised as damaged in this particular country. Please refer to the 'Damage' section for details.

2020-02

 United Kingdom



Wanted

The vehicle was declared as stolen in this particular country. It is purely the 'origin of theft', and does not cover all the jurisdictions otherwise involved.

↑ Close



+31

Data sources

We checked 900+ data sources in 35 countries



Driver & Vehicle Licensing Agency



Driver & Vehicle Standards Agency

Partners

Fuelling this report

